



Tel: (242) 397-5509, 5513, 5514, 5520  
 24 hr. Mobile: (242) 376-1617, (242) 376-8334  
 Fax: (242) 327-2192  
 2<sup>nd</sup> Floor, Manx Corporate Center  
 #45 West Bay Street  
 P. O. Box CB-11702  
 Nassau, N. P., Bahamas  
 Website: [www.baaaid.org](http://www.baaaid.org)  
 Email: [baaid@bahamas.gov.bs](mailto:baaid@bahamas.gov.bs)

The following Safety Recommendation was issued as a result of the AAIA Aviation Accident Report derived from investigation file number A19-000016, an accident which occurred on 5<sup>th</sup> May, 2019 at the Lynden Pindling Int'l Airport Nassau, Bahamas involving Piper Aztec C6-TIM that had a nose gear collapse. Safety recommendation were issued on 22<sup>nd</sup> May 2019 and final report published on 24<sup>th</sup> May, 2019.

Safety Recommendation Number	Safety Recommendation Recipient	Safety Recommendation Text
SI-19-0014	Bahamas Civil Aviation Authority (BCAA)	Recommends the BCAA increase its surveillance activities to ensure aerodrome operators are complying with their obligation to mitigate hazards within their facilities in accordance with the Bahamas Civil Aviation General Regulations (CAGR).
SI-19-0016	Odyssey Aviation	Recommends that Odyssey Aviation takes measures to address the hazardous condition of the paved surfaces in the ramp area at the General Aviation Center.