


# SAFETY RECOMMENDATION SR18-047

## Details


|  |   |
|--|---|
| Synopsis                                   | <p>On 9<sup>th</sup> January 2018, an Embraer Bandeirante (EMB-110), aircraft, registration C6- MIC, registered to Pineapple Air Limited, (a Bahamas Air Operator Certificate (AOC) holder), operating as Pineapple Air flight 978 was involved in a runway excursion accident at the Governors Harbor Int'l Airport, Governors Harbor, Eleuthera, Bahamas.</p> <p>Information received was that at approximately 8:05 pm, after landing, the left main landing gear of the aircraft collapsed, resulting in a runway excursion to the left side of runway 33.</p> <p>The aircraft departed the Lynden Pindling International Airport (LPIA) at 7:00 pm on an instrument flight plan with a total of seventeen (17) on board, (2 crew and 15 passengers).</p> <p>Post-crash investigations uncovered the aircraft attempted a landing on runway 15 at Governors Harbor Airport, but a go-around was executed when visual contact was lost due to heavy rain. On the second landing attempt, the decision was made to switch to runway 33.</p> <p>While on final approach to runway 33, visual contact was lost once again, and a second go-around was executed. On the third and final attempt, a hard landing was made on runway 33, however, 2 seconds after touchdown the left main landing gear collapsed resulting in a runway excursion on the left side of runway 33.</p> <p>Heavy rain occurring at the time of the landing around 7:40pm prevented a rescue attempt by firemen stationed at the airport. Weather conditions were described as severe, at the time of the accident. Several severe weather warnings for the Northwest and Central Bahamas including Eleuthera were forecasted and included heavy rain showers, gusty winds, and thunderstorms. These conditions were all present at the time of touchdown. Weather has been determined to be a contributing factor in the accident.</p> |
| Recommendation                             | <b>To the Bahamas Civil Aviation Authority Safety Oversight Department.</b> The AAIA Recommends that the Bahamas Civil Aviation Authority Safety Oversight Department review and scrutinize all required documents received from check airmen establishing airmen's qualification and proficiency, and ensure those documents correctly reflect the authorizations to be exercised.   |
| Original Recommendation Transmittal Letter | <br>SOD Rec 021, 22, 46, 47, 48.pdf  |
| Overall Status                             | Open – Await Response   |
| Location                                   | Governors Harbor, Eleuthera, Bahamas  |
| Accident Number                            | A18-000002  |
| Accident Report                            | Runway Excursion  |

# SAFETY RECOMMENDATION SR18-047

## Details

|                       |  |
|-----------------------|--|
| Accident Date         | 9 <sup>th</sup> January, 2018            |
| Issue Date            | 31 August, 2018                          |
| Date Closed           |  |
| Addressee(s)          | Mrs. Juliea Brathwaite-Rolle Manager SOD |
| Addressee(s) Response | Open - Await Response                    |

## Safety Recommendation History

|          |   |
|----------|---|
| From     | AAIA  |
| To       | BCAA/SOD  |
| Date     | 31 August, 2018   |
| Response | <br>SOD Rec 021, 22, 46,<br>47, 48.pdf |

|          |  |
|----------|--|
| From     |  |
| To       |  |
| Date     |  |
| Response |  |

|          |  |
|----------|--|
| From     |  |
| To       |  |
| Date     |  |
| Response |  |

|          |  |
|----------|--|
| From     |  |
| To       |  |
| Date     |  |
| Response |  |

|          |  |
|----------|--|
| From     |  |
| To       |  |
| Date     |  |
| Response |  |